

Building & Pest Inspection Report

Inspection Details

Date / Time of Inspection:

Type of Report:

Building & Pest Inspection

Address of Property:

Client Details

Client Name:

Client Email Address:

Client Phone:

Real Estate Agen. Or cails

Agent Name:

Company:

Mobile:

Email Address:

Ir spector Details

Inspector Name

Inspector Office:

Inspector Phone:

Inspector Email Address:

iSPECT

Building & Pest Inspection Report

iSPEC Building Inspections offers property inspection services for your poperty, by highly qualified inspection experts. Each of the inspectors agrees to comply with and are performance managed against iSPECT's Code of conduct. For further information about your report call 1300 477 328 or for further information on our code of conduct please visit https://ispect.com.au/code-of-conduct



TABLE OF CONTENTS

1. Description of property inspected	4
2. Definitions	
3. Inspection Agreement	7
4. Terms & Conditions	9
5. Hallways and general living spaces	11
6. Kitchen	12
7. Laundry	17
8. Bedrooms	18
8.1. Bedroom 1	18
8.2. Bedroom 2	20
8.3. Bedroom 3	21
8.4. Bedroom 4	23
9. Bathrooms	24
9.1. Bathroom 1	24
10. Ensuite	28
10.1. Ensuite 1	28
11. External of property > Exterior	32
12. External of property > Roof areas	35
13. External of property > Sub flor careas	37
14. Timber pest areas inspected	38
15. Timber pest inspect in find gs and recommendations	39
16. Timber pest contained additions	40
17. Timber pest Term & and nons	42
18. Report file Yes - sur many	44
19. iSPECT Builds a Inspections	45

1. Description of property inspected

Brief description of the building and other structures on the property:

Туре:	Freestanding House	Domestic
Bedrooms:	4	
Bathrooms:	1	
Ensuites:	1	
Car Park:	Single	
Height:	Single Story	
Building:	Brick Veneer	
Piers:	-	
Floor:	Slab	
Roof:	Metal	
Age:	1990s	
Image of property:		





weather at	time of inspection?
Fine	
Was the pr	operty furnished at time of inspection?
No	
Please note:	To conduct an inspection in accordance with AS 4349.1 the property would be vacant of all furnishing to enable a thorough visual inspection.
Was there	evidence of any extensions at time of inspection?
No	
Comment:	
Services co	onnected to property
Electricity:	Yes - Not tested
Comment:	
Gas:	Yes - Not tested
Comment:	
Water:	Yes - Not tested
Comment:	
Sewer:	Yes - Not tested
Comment:	
Drainage:	Yes, ot tester
Comment:	
Smoke Detec	Yes Vot tested
Comment:	



2. Definitions	
Definition of terms used t	to describe the current state of repair for each item inspected
Condition Visually Fine:	When the Inspector has viewed the subject area and sees no major defect, and sees no safety hazard.
General Advice/Minor Defect	A general impression regarding the extent of minor defects. Minor defects are common to most properties and may include minor blemishes, corrosion, cracking, weathering, general deterioration, unevenness, and physical damage to materials and finishes, such as desilvering of mirrors. It is expected that defects of this type would be rectified as part of normal ongoing property maintenance.
Major Defect	A defect of sufficient magnitude where repair works must be carried out, in order avoid unsafe conditions, loss of utility or further deterioration of the property. Recurs shall be carried out by a suitably qualified or licenced trades person. A Major Defend where is safe conditions are immediately present and which must be repaired at the expectation.
Unable to Inspect Due to access:	An area of the site where there is insufficient, unsafe or unrease able access.
Not Applicable (N/A):	When the subject field doesn't make up any part of the inspe
Report Definition	
Shower Recesses:	Tests may be made on shower recesses to detect learn water is connected). The tests may not reveal leaks or show incorrect water profing if shown liquid or masonry sealant has been applied prior to the inspection. Such application is emporary waterproofing measure and may last for some months before reaking sown. They also of shower recesses are limited to running water within the recesses and visually checking for leaks. As shower are only checked for a short period of time, purposed us may reveal leaks were not detected at the time of inspection. No purpose of a content lask during inspection does not necessarily mean that the sower dies not les
Glass Caution:	Glazing in some building (but wore 1976) may not necessarily comply with current glass safety standards AS1288. In the sterests of safety, glass panes in doors and windows especially in high traffic areas should be replaced with safety glass of have shatterproof film installed.
Stairs & Balustrades:	The Australian Built of Code 3.9 require that covering stairs, landings and balustrades ensure the fet of all occupants and visitors to a building. Those built prior to 1996 may not comply with the curry of standard. You must upgrade all such items.
Swimming Pools:	A pol is subject to a special purpose property report and is not applicable to this report.
Rooms Below Ground Level	Joms by the house or below ground level (whether they be habitable or not) may be ubject to dampness and water penetration. Drains are not always installed correctly to these areas or could be blocked. It is common to have damp problems and water entry into these spaces, especially during periods of heavy rainfall and may not be evident on the day of the visual inspection. These rooms may also not have council approval. The purchaser hould make their own enquiries to Council to ascertain if approval was granted.
Owners Corporation	If the property is covered by an Owners Corporation (Strata Title) iSPECT recommend that an Owners Corporation search be conducted to ascertain their financial position, the level of maintenance afforded and any other relevant information that may impact your future ownership of the property.



3. Inspection Agreement

Requirement for inspection agreement

AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building ar which is in reasonable condition, having been adequately maintained over the life of the building. This means that building inspected may not comply with Australian Standards, building regulations or specific state or territory requirements app the time of the inspection.

Purpose of inspection

The purpose of the inspection is to provide advice regarding the condition of the property at the time of the in

Reasonable Access to the property at time of inspection?

Yes

Limited access to the roof space due to heating ducts, and a as of the ro being low Note: lying not allowing for bodily access.

Areas where reasonable entry is denied to the inspector or where reasonable ilable are excluded from and do not form part of the inspection. Access limitations may include legal righ ked dog security system, pets, furniture or other obstructions. Physical access limitations may include height boun rance, thick vegetation, small roof or crawl space and adverse weather conditions. The report shall ig within the scope of the inspection that tify an rea or i

was not inspected and the factor that prevented inspection.
The extent of accessible areas shall be determined by the inspe representation is a spection based on the conditions areas and areas that are within the inspector's line of sight encountered at that time. The inspection shall include only access and close enough to enable reasonable appraisal.

Reasonable access includes a prerequisite that the imum clearance pecified in the table below are safely available. Dimensions for reasonable access:

- 600mm crawl space; and accessible from a 3.6m ladder; Roof Interior: 400mm x 500mm access hole
- Roof exterior: 400mm x 500mm access hole; 6 crawl space; and accessible from a 3.6m ladder placed on the ground

Supplementary notes:

- Reasonable access does not it cutting of ccess holes or the removal of screws and bolts or any other fastenings or sealants to access covers.
- · Sub-floor areas sprayed be inspected unless it is safe to do so. th chei cals à

Conditions

An inspection report n al on: ond

- itio or recent occupancy and use of services that mightaffect observations. the client or agents of the client. Prevailir her co
- Informati
- Deliberate d f defects.
- factor limiting the inspection. other rele

Scop Of 115p _tion

t reported on, general exclusions detailed in AS 4349.1 – 2007

- a building that are under construction;
- nspection is not intended to include rigorous assessment of all building elements in a property;
- ects that would only be apparent under particular weather conditions or when using particular fittings & fixtures;
- efects not apparent due to occupancy or occupancy behaviour e.g. non-use of a leaking shower; • The inspection report is not a certificate of compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing with the building in the future;
- Unauthorized building work or of work not compliant with building regulations;
- Title and ownership matters, matters concerning easements, covenants, restrictions, zoning certificates and all other lawrelated matters:
- Estimation of the cost of rectification of specific defects.

What is not reported on, specific exclusions detailed in AS 4349.1 - 2007

· Footings below ground, concealed damp-proof course, electrical installations, operation of smoke detectors, light switches and fittings, TV, sound and communication and security systems, concealed plumbing, adequacy of roof drainage as installed,



gas fittings and fixtures, air conditioning, automatic garage door mechanisms, swimming pools and associated filtration and similar equipment;

· The operation of fireplaces and solid fuel heaters, including chimneys and flues, alarm systems, intercom systems, soft floor coverings, electrical appliances including dishwashers, incinerators, ovens, ducted vacuum systems, paint coatings except external protective coatings, health hazards e.g., allergies, soil toxicity, lead content, radon, presence of asbestos or urea formaldehyde), timber and metal framing sizes and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment (such as gates, inclinators);

· Soil conditions, control joints, sustainable development provisions, concealed framing-timbers or any areas concealed by wall linings or sidings, landscaping, rubbish, floor cover, furniture and accessories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmental provisions, energy efficiency, lighting efficiency.

What is reported on

The inspection includes subjective appraisal by an inspector competent to assess the condition of residential buildings. It involves a subjective assessment so different inspectors or even the same inspector on a different occasion may reach different conclusions.

The inspection comprises a visual assessment of the property to identify major defects and to form an opinion re general condition of the property at the time of inspection. The following areas shall be inspected where appli

- The interior of the building: ceilings; walls; floors; windows; doors & frames; kitchen; bathroom; WC; ensuit damp problems;
- The exterior of the building: walls (including lintels, claddings, doors & windows); timber or steel chimneys; stairs; balconies, verandas, patios, decks, suspended concrete floors, balustrades;
 The roof exterior: roof (including tiles, shingles & slates, roof sheeting, gables, flashings); skylig
- s, vents, flu guttering; downpipes; eaves, fascia's and barges;
- The roof space: roof covering; roof framing; sarking; party walls; insulation;
- floors;
- The sub-floor space: timber floor (including supports, floor, ventilation, drainage, dap
 The property within 30m of the house and within the boundaries of the site: car acc moda laundry, ablution facilities and garden sheds; retaining walls (where supporting other structures and la paths & driveways; steps; fencing (general & swimming pool); surface water (drainage taining walls > 700mm high); caping



4. Terms & Conditions

iSPECT Terms & Conditions

General

- 1. iSPECT Building Inspections (iSPECT) has prepared this report in accordance with the guidelines of **Australian Standard 4349.1 2007 Inspection of buildings Part 1: Pre-purchase inspections Residential Buildings** (the Standard) which covers the minimum requirements for the visual inspection of residential buildings and based on the inspection of the property by the Inspector named in the building inspection report.
- 2. The Report is prepared for the sole and exclusive use of the Client (person, persons or body) named in the Booking Confirmation and cannot be used or acted upon by any other party without the express permission of iSPECT.
- 3. The Terms and Conditions are available on the website: www.iSPECT.com.au and can change without notice.
- 4. The Client, having been provided with the opportunity to read these Terms and Conditions following the making of a soking and a payment for an inspection, accepts these Terms and Conditions.
- 5. The Client acknowledges that these Terms and Conditions take precedence over any oral or written protection made by iSPECT or the Inspector, to the extent of any inconsistency.
- 6. A report prepared in accordance with the Standard is not a certificate of compliance of the property within the quirements of any Act, regulation, ordinance, local law or by-law, or as a warranty or an insurance policy against publems developing with the building in the future.

The Inspection

- 7. All inspections will be a **non-invasive visual** inspection and will be limited to the seasonable Access (see below) is both available and permitted on the date application.
- 8. The inspection is undertaken, and the Report prepared, by the Inspector, the committee that the existing use of the Inspected Property will continue. As such, the Inspector will not assess the fit as of the Inspected Property for any other intended purpose. We advise you to verify any proposed change in property with the relevant authorities.
- 9. Where the Inspected Property is a unit or apartment (Strata 7 1.6), inspected areas, all be limited to the nominated residence and does not include common property. i.e. Only those items is ad on the shall be reported.
- 10. The Inspected Property shall be compared with a building that it is constructed in accordance with the generally accepted practice at the time of construction and which has been maintained so that there has been no significant loss of strength and serviceability.

Reasonable Access

- 11. The Standard provides that "safe and reasonable ccess" standard provides that "safe and reasonable ccess" standard provides that the time of the inspection, based on the conditions encountered at the time of the ectic. An inspector shall only inspect areas where safe, unobstructed access is provided and where the mixtuum clearances are vailable or, where these clearances are not available, areas within the inspector's unobstructed line of sight and close enough to enable reasonable appraisal.
- 12. Minimum clearances are defined at less 600 cm vertical and horizontal clearance for roof space and sub floor area access. The interior and exterior roof must be coessis. From a 3.6 metre high ladder for reasonable access to be available.
- 13. Reasonable access toes Nor does reasonable access include cutting or making access trail moving purniture or stored goods.

Limitations

- 14. **No assess** (a) **ride tification** is made of asbestos or asbestos related products, toxic mould, Methamphetamine or other harmful substants. As a set is a hazardous material and should not be disturbed. It is vital that asbestos is not sawn, sanded, drilled or other blacked, etc. For more information about the handling and disposing of asbestos contact your local could be.
- 15. Our nspecious es not assess the operation of appliances, alarms, security and communication systems, smoke detectors, heating a cooling systems, blinds (internal and external), soft furnishings, telephones, spa and pool equipment, building automaten, electrically operated doors, plant and equipment. Any item not specifically noted in this Report is excluded from the interaction of the Inspected Property. We suggest that a licensed tradesperson be contacted for a separate report in respect of gas refer tick, appliance and fittings.
- 16. No tem of furniture or fixtures will be removed, moved or modified during the inspection and items and conditions covered the ch furnishings and fixtures are not inspected or considered. Nor do we assess the condition of conspicuous, non-structural items such as carpets, vinyl floor coverings etc.
- 17. The Inspector can only make comment about the general, visible condition of electrical wiring and plumbing. We suggest that a licensed tradesperson be contacted for a separate report.

The Inspection Report

18. The Report must be read carefully and, in its entirety, to gain a complete understanding of the findings of the inspection of the Inspected Property. It will help you understand the limitations faced by an inspector and why it is not possible to guarantee that a property is completely free of defects.



- 19. This Report describes the visual assessment of the Inspected Property including: the relevant features of the Inspected Property within 30m of the building and within the boundaries of the site, the prevailing structural, soil and weather conditions at the date and time of the inspection.
- 20. The Report is a subjective assessment of the Inspected Property and therefore outlines the opinion of the Inspector on the general condition of the Inspected Property at the date and time of the inspection in relation to major defects or safety hazards and a general advice on minor defect items.
- 21. The Report does not cover any part of the building located beneath the ground surface or identify any unauthorised building work or of work not compliant with building regulations.
- 22. An estimate of the costs of rectification of defects is not required in accordance with the Standard.
- 23. Any maintenance and general advice items are intended as a helpful guide. The Report is not an exhaustive list of all maintenance and advice items.
- 24. The Report provides no guarantee and is not a warranty against problems developing with the Inspected Property future.
- 25. This Report is not a rigorous assessment of all building elements and does not cover all maintenance items. It is produced does not cover defects in inaccessible areas, defects that are not reasonably visible, defects that may only be apply at in certain weather conditions or defects that have not yet arisen due to prolonged periods of wet or dry weather conditions or defects that have not yet arisen due to prolonged periods of wet or dry weather conditions.
- 26. The Building or Pre-purchase Inspection Report does not identify the presence of timber pests, rany damage aused by timber pests (e.g. termites, borers, etc.). If you wish to include this, you will need to request a Timber Pest inspection report. If there is a concern regarding other types of pests then a fully qualified Pest Controller shows a point and.

Other matters

- 27. You should address legal and conveyancing matters such as title and owners to be you dicitor or legal representative. Compliance issues in relation to the positioning of services, privacy, vehicle access, the siting of the buildings, zoning, permit or town planning issues or other legal matters should be directed to the relevant authority or to a dicitor or legal representative.
- 28. Unless otherwise notified, iSPECT Building Inspections will make vendor, as a sed reputs available to prospective buyers. Please advise within 48 hours of receipt of this report if, as a vendor prospective purchasers of the property.



5. Hallways and general living spaces





	Condition Visually Fine	General Advice/Minor Defect	Major Defect	Ur ic Ins, it Due to icess	Not Applicable
Floor	₫				
Walls	₫				
Ceilings	₫				
Doors		I			
Windows	I				
Fireplace					₫
Stairs					₫
Balustrade					₫

Hallways and general living s

General Advice/Minor De

Doors

Comments

Entry, it has been observed that the door appears to be binding on the top left-hand side of the door jamb.







6. Kitchen





	Condition Visually Fine	General Advice/Minor Defect	Major Defect	Unz In. ct Due	Not Applicable
Floor	₫				
Walls		Ø			
Ceilings	₫				
Doors	₫				
Windows	₫				
Cabinets / Drawers		ď			
Benchtops	₫				
Sink/Taps	₫ _				
Appliances (Oven, Range Hood, Dishwasher)					
Ventilation	$\overline{\square}$				

General Advice/Minor Defect

Cabinets / Drawers

Comments

It has been observed that the shelving/cabinet below the sink appears to be water damaged.









General Advice/Minor Defect

Cabinets / Drawers

Comments

It has been observed that the hinge associated with the bottom left hand side cabinet door, appears to have become detached from the door.





Kitchen

General Advice/Minor Defect

opliants (Over 20 ge Hood, Dishwasher)

Comments

It has been observed that the oven door is difficulate fully open, a ppears the hinges are binding on the oven frame.





General Advice/Minor Defect

Appliances (Oven, Range Hood, Dishwasher)

Comments

It has been observed that the battery for the gas cooktop spark igniter appears to be missing.





Kitchen

General Advice/Minor Defect

A pliants (Ove Range Hood, Dishwasher)

Comments

It has been observed that the plastic cover for the rangehood lightlight switch off button appears to be damaged.







General Advice/Minor Defect

Walls

Comments


It has been observed that the split system appears not to be engaging, when attempted to connect with the wireless remote controller.








7. Laundry



	Condition Visually Fine	General Advice/Minor Defect	Major Defect	Une to reess	Not Applicable
Floor	₫				
Walls	₫				
Ceilings	₫				
Doors	₫				
Windows	₫				
Trough/Sink	₫				
Taps	₫				
Cabinets	₫ ,				
Sealants	Ø				
Exhaust Fans					₫
Ventilation	F				

8. Bedrooms

8.1. Bedroom 1



	Condition Visually Fine	General Advice/Minor Defect	Major Defect	nable to nspect Due Access	Not Applicable
Floor	₫				
Walls	₫				
Ceilings	₫		<u>1</u>		
Doors	₫				
Windows	₫				
Robes					
Smoke Detectors					₫

Bedroom 1

General Advice/Minor Defect

Robes

Comments

It has been observed that the right hand side robe doors appeared to be misaligned, the front and rear skins of the door appear to be delaminating and the left hand side robe doors appear to be binding.





8.2. Bedroom 2



	Condition Visually Fine	General Advice/Minor Defect	Major Defect	Unable to I pect Due	ot Applicable
Floor	₫				
Walls	₫				
Ceilings	₫				
Doors	₫				
Windows	₫				
Robes					₫
Smoke Detectors					Ø

8.3. Bedroom 3 General **Condition Visually** Unable to I pect Due Advice/Minor **Major Defect** ot Applicable Fine 1cc Defect Floor Walls ₫ Ceilings ₫ **Doors** ₫ Windows Robes **Smoke Detectors** ₫ **Bedroom 3 General Advice/Minor Defect** Robes Comments It has been observed tha doors appear to be misaligned and binding



Bedroom 3

General Advice/Minor Defect

Windows


Comments

It has been observed that the window lock catch does not engage with the window frame, preventing the window from being locked.









	Condition Visually Fine	General Advice/Minor Defect	Major Defect	Unable to I pect Due	ot Applicable
Floor	₫				
Walls	₫				
Ceilings	₫				
Doors	₫				
Windows	₫				
Robes	₫				
Smoke Detectors					₫



9. Bathrooms

9.1. Bathroom 1





	Condition Visually Fine	General Advice/Minor Defect	Major Defect	nable to inspect Due Access	Not Applicable
Floor	₫				
Walls	₫				
Ceilings		I			
Windows	đ				
Doors		ď			
Shower Recess					
Shower Screen	₫ 🛕				
Shower Rose	Ø	U			
Bath	M				
Taps	F				
Cabinets		₫			
Seala .					
Basins	V				
Tons	ď				
Ve ،ation	₫				

Bathroom 1

General Advice/Minor Defect

Shower Recess

Comments

It has been observed that appears to be some mould occurring to the shower recess area.





Bathroom 1

General Advice/Minor Defect

alige.

Comments

It has been observed that one of the heat lamps to the IXL appear to be burned out.





Bathroom 1

General Advice/Minor Defect

Shower Recess

Comments

It has been observed that there was an elevated moisture reading detected with the moisture meter, to the bottom section of both tiles walls in the shower recess area.









Bathroom 1

General Advice/Minor Defect

Cabinets

Comments

It has been observed that the shelving/cabinet below the basin appears to be water damaged.





Bathroom 1

General Advice/Minor Defect

D' JIS

Comments

WC, it has been observed that the bottom right hand side of the lar appears to be binding on the door jamb.







10. Ensuite

10.1. Ensuite 1





	Condition Visually Fine	General Advice/Minor Defect	Major Defect	nable to inspect Due of Access	Not Applicable
Floor	₫				
Walls	₫				
Ceilings		I			
Doors	₫				
Windows	₫				
Shower Recess		F			
Shower Screen	₫ _				
Shower Rose	Ø	N			
Bath	☑				
Mixer Taps	F				
Cabinets		Ø			
Sealá .					
Basins	d				
Tone	ď				
Ve. "ation	₫				

Ensuite 1

General Advice/Minor Defect

Shower Recess

Comments

It has been observed that there appears to be some mould occurring to the shower recess area.








Ensuite 1

General Advice/Minor Defect

Shower Recess

Comments

It has been observed that there appears to be 2 cracked wall tiles located to the bottom corner of the shower recess area.





Ensuite 1

General Advice/Minor Defect

Cabinets

Comments

It has been observed that the shelving/cabinet below the basin appears to be water damaged.





Ensuite 1

General Advice/Minor Defect

alige.

Comments

It has been observed that one of the heat lamps to the IXL appear to be burned out.





11. External of property > Exterior								
	Condition Visually Fine	General sually Advice/Minor Major Defect Defect		Unable to Inspect Due to Access	Not Applicable			
Walls	₫							
Windows	₫							
Doors	₫							
Fascia, Eaves, Bargeboards	₫							
Down Pipes	own Pipes							
Deck, Verandah, Balcony, Patio					Ø			
Steps				Ţ	M			
Handrails					Ø			
Pergola		₫						
Driveways and Paths	s and Paths							
Retaining Walls					Ø			
Garage/Car Port	₫							
Fence	₫							
Site Drainage	ব			П	П			



External > Exterior

General Advice/Minor Defect

Pergola

Comments

It has been observed that a number of the timber beams to the outdoor living area appear to be weather/damaged rotted.









External > Exterior

Condition Visually Fine

Walls

Comments

General photos of the left, rear and right elevations.









12. External of property > Roof areas

Roof Type:





	Condition Visually Fine	General Advice/Minor Defect	Major Defect	nable to inspect Due . Access	Not Applicable
Roof Space	₫				
Roof	₫				
Valleys	₫				
Flashings	₫				
Gutters	₫				
Pointing					₫
Skylights					₫
Vents	Ø				
Chimney					₫

External > Roof Areas

Condition Visually Fine

Roof Space

Comments

General photos of the roof space.







13. External of property > Sub floor areas

	Condition Visually Fine	General Advice/Minor Defect	Major Defect	Unable to Inspect Due to Access	Not Applicable	
Sub Floor Ventilation					₫ 🎤	
Stumps					Ø	
Framing					ď	



14. Timber pest areas inspected

Requirement for timber pest inspection agreement

This report is the result of a Visual Inspection Only. Inspection of the subject property and this report has been completed with reference to AUSTRALIAN STANDARD AS 4349.3 - 2010 Inspection of buildings Part 3: Timber Pest Inspections. The report is intended to be read as a whole, please read our detailed inspection information 3.5 Scope of Inspection, which includes a number of important disclaimers.

Important Note

It is strongly recommended that a full pest inspection be undertaken every 6-12 months. Regular inspections DO NOT stor pest attack, but are designed to limit the amount of damage that may occur through early detection.

Are	as Inspected
Whei	re applicable and where there is reasonable access, the following areas are examined during our inspection
✓	Interior and exterior of structures
✓	Roof cavity
✓	Garage or carport
	Subfloor
V	Retaining walls and garden borders
✓	Garden and storage sheds
✓	Structures, fences and trees within Pom of the building within the boundaries of the property
✓	Pergolas and decks
Rep	oort on Areas Inspectation
Ourv	visual inspection is unto taken to identify the following timber pests:
V	Subterranean en ite ad vity or damage
√	Borer at livits
V	Vood Cay (Nt) fungi damage



15. Timber pest inspection findings and recommendations								
	Condition Visually Fine	Activity or Damage Advice on Item	Action Recommended	Major Structural Defect	Unable to Inspect Due to Access	Not Applicable		
Dwelling	₫							
Interior	Ī							
Windows	Ī							
Door Frames	₫							
Roof Cavity	₫							
Sub Floor						Ø		
Garage/Carport	₫							
Fence line	₫							
Grounds	₫							
Retaining Walls						₫		
Garden Borders	₫							
Pergola	₫							
Deck						Ø		
	₫		D					



₫

Outbuildings

16. Timber pest conducive conditions
Areas Conducive
Timber Pest attacks are likely to occur if the following items are not considered and planned for:
Hot water system overflow should be directed away from building or to a drain
External timbers in contact with the building may allow termites to enter undetected
✓ Landscape timbers should be removed or replaced with treated timbers
✓ Weepholes in brick work need to be free from soil
Note:
Report on Drainage
A visual inspection is undertaken to identify potential drainage problems:
✓ Concrete slab
☐ Stumps
✓ Other
Note: Poor subfloor drainage increases the likelihoof termit attack. If drainage is considered inadequate, a plumber or other building expert should be consulted.
Note:
Report on Ventilatio
A visual inspection is u to taken identify potential ventilation problems:
✓ Concrete lab
□ tump
Oth -
Note: Intilation of the sub-floor region is important in minimising the opportunity for subterranean termites to establish ther elves. If found to be inadequate, remedial measures should be taken. You should explore arranging the installation of high low vents and/or improve the cross flow of air within the subfloor, so as to produce ventilation equivalent to 8400 sq mm net ventilation area per lineal metre on external and internal walls.
Note:



Evid	ence of Possible Termite Tr	eatr	nent			
A visu	al inspection is undertaken to identify e	evide	nce of possible termite treatn	ment:		
✓	Concrete slab					
	Stumps					
✓	Other					<u> </u>
Note:	There was no evidence of possible te	rmite	treatment.			
Sub	terranean Termite Treatme	nt R	ecommendation			
	e time of the inspection it is our opinior rol or prevent subterranean termites fro				rith Aut Falian Stands d	3660.1 to
	High [√	Moderate	, (W	
Ove	rall Degree of Risk of Timber	r Pe	st Infestation			
Cons	idering all of the relevant factors, it is o	ur op	inion that the overall degre	of sk of terr	te infestation to the pr	operty is:
	High [✓	Moderate		Low	
and t struc in co the ri It sho to ma or fre	The overall degree of risk of Timber Petition, taking into account many factors rees and/or other timber structures, the ture or within the inspected structure, on that with soil, inaccessible areas, slabsk of future timber pest attack, ould be noted that if the risk factor is higher them aware that increased vigilance quency of inspections should be observed and the structure of the degree of pest in state fied pest inspection every six to the text of the section of	gh, i.	serve of evidence of the ber power conditions that raise the bound construction etc, or other appropriate of the ber power appropria	est damage of e potential of her factors that chaser from partions regar	r activity close to the in timber pest attack, sucl t, in the inspector's opi urchasing the property ding reducing conduciv	spected h as timbers nion, raise ; it is simply e conditions



17. Timber pest Terms & Conditions

Genera

1. iSPECT Building Inspections (iSPECT) has prepared this report in accordance with the guidelines of Australian Standard AS 4349.3-2010 Inspection of buildings Part 3: Timber pest inspections (the Standard).

- 2. The Report is prepared for the sole and exclusive use of the Client (person, persons or body) named in the Booking Confirmation and cannot be used or acted upon by any other party without the express permission of iSPECT.
- 3. These Terms and Conditions are available on the website: www.iSPECT.com.au and can change without notice.
- 4. The Client, having been provided with the opportunity to read these Terms and Conditions following the making of a board and a payment for an inspection, accepts these Terms and Conditions.
- 5. The Client acknowledges that these Terms and Conditions take precedence over any oral or written representations deby is precedence over any oral or written representation of the Inspector, to the extent of any inconsistency.
- 6. Timber Pest Inspections will be carried out within and around existing buildings and structures.
- 7. A copy of the Australian Standards may be obtained from Standards Australia.
- 8. No responsibility is accepted, or warranty implied, for any timber damage that may occur as the sult of past, urrents returned termite activity as termites can gain access to a structure at any time.

The Inspection

- 9. All inspections will be a non-invasive visual inspection and will be limited to those are and stions operty to which Reasonable Access (see below) is both available and permitted on the date and time an aspectic
- 10. The Report will state timber damage found as 'low, 'moderate' or 'high'. This formation is not the opinion of an expert, as the inspector is not qualified to give an expert opinion.
- 11. The inspector may use a probe, donger or screwdriver to tap and sound ome tirevers.
- 12. The inspector may use a moisture meter to check moisture levels it walls to back on wet areas such as showers etc. Other than these areas the moisture meter will not be used on other surfaces every two a the risual inspection indicates that there may be a need to further test the area.

Reasonable Access

- 13. The Standard provides that "safe and reasonable access" shall be determined by the inspector at the time of the inspection, based on the conditions encountered at the time of inspection. An inspect or shall only inspect areas where safe, unobstructed access is provided and where the minimum clearant is are available or, were these clearances are not available, areas within the inspector's unobstructed line of sight and close exactly to enable reasonable appraisal.
- 14. Minimum clearances are defined as at least communication and horizontal clearance for roof space and sub floor area access. The interior and exterior roof must be accessible in the 3.6 method high ladder for reasonable access to be available.
- 15. Reasonable access does not include removing screening a bolts to access covers. Nor does reasonable access include cutting or making access traps or moving further ending access traps or moving further ending access.

Limitations

- 16. The inspector cannot set of inspections decrease, between floors, inside skillion roofing, inside the eaves, behind stored goods in cupboards, in other area of that are oncealed or obstructed. Insulation in the roof void may conceal the ceiling timbers and make inspection of the area of safe.
- 17. No item of furniture a sixtures will be removed, moved or modified during the inspection and items and conditions covered by such furnishings and like as are at inspected or considered.
- 18. If the process has be in sectal is occupied then you should be aware that furnishings or household items may be concealing evidence of Timer Park and sich may only be revealed when the items are moved or removed. In some cases, the concealment may be deliberate
- 19. The inspection wilk, of involve any invasive inspection including cutting, digging, gouging, force breaking apart, dismantling, removing or consequences including, but not limited to, roofing, wall and ceiling sheeting, ducting, foliage, mouldings, debris, roof inside on, sarking, sisalation, floor or wall coverings, sidings, fixtures, floors, pavers, furnishings, appliances or personal cossess. Its.
- unged an invasive inspection a fully qualified Pest Controller would need to be engaged. After an invasive Timber Pest Inspection is carried out, you may need to arrange for a qualified person such as a Builder, Engineer, or Architect to carry out a struct al inspection and to determine the full extent of the damage and the extent of repairs that may be required.
- Whilst trees on the property up to a height of 2m have been visually inspected, where possible and practicable, for evidence of termite activity it is difficult to ascertain whether termite nests are present. This is because they are generally well concealed and located either underground or in trees. We recommend that any trees on the property are inspected and drilled by a fully qualified Pest Controller.

Determining Extent Of Damage

- 22. Termites can attack any structure. Periodic maintenance should include measures to minimise possibility of infestation in an around the property.
- 23. Some factors leading to infestation may include when the concrete slab is covered by soil or garden debris, soil filled area or areas with less than 400mm clearance, foam insulation at foundations, poor drainage, leaking pipes, damp areas, formwork



timbers, scrap timbers, tree stumps, mulch, tree branches touching the structure, wood rot and timber retaining walls, garden pathways, or turf abutting or concealing the edge of a concrete slab and retaining walls. The Report will not and cannot state the extent of any timber pest damage.

- 24. If any evidence of Timber Pest activity and/or damage resulting from Timber Pest activity is reported either, within the structures or the grounds of the property, then damage may exist in concealed areas, e.g. framing, then you should assume that there may be some structural or concealed damage within the building(s).
- 25. If Timber Pest activity and/or damage are found then an invasive inspection is strongly recommended. Damage may only be found when wall linings, cladding or insulation are removed to reveal previously concealed timber. You agree that neither we nor the iSPECT Inspector is responsible or liable for the repair of any damage whether disclosed by the report or not.

Other Matters

26. If you are the purchaser and not the owner of the property to be inspected then you should obtain a statement from the owner as to any timber pest activity or damage to the property known to them and what, if any, treatments have been carried out to the property. It is important to obtain copies of any paperwork issued and the details of any repairs carried out. Ideally the information obtained should be given to the inspector prior to the inspection being conducted.

27. Unless otherwise notified iSPECT Building Inspections will make vendor purchased reports available to projective divers. Please advise within 48 hours of receipt of this report if, as a vendor, you do not wish this report to be made available prospective purchasers of the property.

Understanding

28. If there is anything that you do not understand then, prior to the commencement of the inspection, you must pentact us by phone or in person and have us explain and clarify the matter to your satisfaction. Your failure to a stact us or call the requested inspection means that you have read these terms and conditions and that you do fully understand the potents.

Note: Additional inspection requirements requested by you may incur additional expert a regarding the inspection.

Definitions

You should read and understand the following definitions of words used in this at element of the Report. This will help You understand what is involved in a Timber Pest Inspection or a Termite Inspection, the difficult is faced by an inspector and the contents of the Report with which we will provide you following the inspection.

Access hole means a hole in the structure allowing entry to an area.

Active means live timber pests were sighted during the inspection

Client means the person(s) who requests the report. If ordered the client and has the authority to act for and on behalf of the client and has the authority to act for and on behalf of the client and has the authority to act for and on behalf of the client and has the authority to act for and on behalf of the client and has the authority to act for and on behalf of the client and has the authority to act for and on behalf of the client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority to act for any other client and has the authority and has the

High moisture readings mean a reading on a moisture meter that is a ther that the norm for other parts of the structure. Such high reading should be investigated by invasive means as the presence could indicate a leak or may indicate timber pest activity and damage.

Inactive means that no active (see definition above) the ber pests were detected but evidence such as workings, damage, mudding or exit holes is found at the time of the inaction.

NOTE: Where visual evidence of inactive termite working and/or damage is located, it is possible that termites may still be active in the immediate vicinity and the termit may continue to cause further damage It is not possible, without benefit of further investigation and inspections or taking, it ascertain mether any infestation is active or inactive. Continued, regular, inspections are essential.

Property means the structures, gardins, trees, fences etc up to thirty (30) metres from the exterior walls of the main building but within the boundaries of the local which the main building is erected. Unless You specifically order in writing that structures, gardens, trees and fellowetcook de the thirty (30) metres from the exterior walls of the main building be inspected no such inspection will be carried.

Reasonable cass mean ton, yeas to which reasonable access is available are inspected. The Australian Standard AS 4349.3-2010 which or the assor ble access. Access will not be available where there are safety concerns, or obstructions, or the space available is less on the space available is less.

Roof Void - the diversions of the access hole should be at least 500mm x 400mm, and, reachable by 3.6 M ladder, and there is at least 500mm x 600mm of space to crawl;

Roof teris yest by accessible by a 3.6M ladder

Subflo r - A zess. Formally not available where dimensions are less than 500mm x 400mm for the access hole and less than 400mm (and space beneath the lowest bearer, or less than 500mm beneath the lowest part of any concrete floor; The inspecto chall determine whether sufficient space is available to allow safe access to confined areas.

cease policaccess does not include the use of destructive or invasive inspection methods. Nor does reasonable access include cutting or making access traps or moving heavy furniture or stored goods.

In order to the state of the state of the state of the property.

Termites means Subterranean and Dampwood termites (white ants) and does not include Dry wood termites.



18. Report findings - summary

This Building Inspection summary provides you with a "snapshot" of the items the inspector considers of greatest significance for you, in respect of the building only, when considering this property. Please refer to the Definitions and the complete Report for detailed information regarding visible defects. Note that this Summary is not the complete Report and that in the event of an apparent discrepancy the complete Report overrides the Summary information.

Report Summary

The home present solid for its age, with the number of items identified at the time of the inspection.

There is the normal expected wear and tear for a home of this age.

Timber pest report summary

There was no timber pest activity identified at the time of the inspection.

Major Defects noted

No

A summary of any major defects found. A defect of surgice of agnitude where rectification has to be carried out without undue delay to avoid: unsafe conditions, pour g a threat to life perious injury; loss of utility, whereby the defect is such that the whole of the relevant part of the building can be longer serve its intended function; or further substantial deterioration of the building.

Major Str. The TD fects Noted

No

A major left of in an internal or external primary load bearing component of the building which seriously affects the structural integrity of the building requiring rectification to be carried out without undue delay to avoid: unsafe conditions, posing a threat to life or prious injury; loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer structural defect in unded function; or further substantial deterioration of the building. In the case of cracking, a serious structural defect serior severe cracking as defined by Category 4, Appendix C – Australian Standard AS 2870-2011.



19. iSPECT Building Inspections

The iSPECT Building Inspections is a national franchise building inspections business. iSPECT engages with trade qualified builders with a minimum of 10 years residential and commercial building experience to complete property inspections. Each home and building inspection completed is then detailed in a report that is complete to Australian Standards AS4349.0, AS4349.1 and/or AS4349.3. iSPECT has franchise nationally who are supported by a national call centre located at 8 Appearso Street, Port Melbourne. Our office locations follow:



